



Australian Government

MEASS00463 AMW006 Aircraft pulse system component repair/overhaul

Release 1

MEASS00463 AMW006 Aircraft pulse system component repair/overhaul

Modification History

Release 1. Skill set code changed. Description added. Units and codes updated. Supersedes and is equivalent to MEASS00250 AMW006 Aircraft pulse system component repair/overhaul.

Description

This skill set reflects the skill requirements for allied trades persons who are to be employed in aircraft component maintenance workshops on aircraft pulse system component repair and overhaul.

Pathways Information

These units provide credit towards a Certificate IV qualification in the MEA Aeroskills Training Package.

Licensing/Regulatory Information

Nil.

Skill Set Requirements

MEA157	Complete aviation maintenance industry documentation
MEA201	Remove and install miscellaneous aircraft electrical hardware/components*
MEA246	Fabricate and/or repair aircraft electrical hardware or parts*
MEA296	Use electrical test equipment in aviation maintenance activities*
MEACOM002 9	Conversion from allied trades for employment in aviation maintenance workshops*
MEAAVI0038	Use electronic test equipment*
MEAAVI0039	Modify and repair aircraft component single-layer printed circuit boards*
MEAAVI0052	Repair and overhaul aircraft pulse system components*

Units marked with an asterisk have prerequisites. See the unit or the MEA Aeroskills Companion Volume Information Guide for details.

Target Group

This skill set is for individuals with Certificate III or Certificate IV qualifications in an allied trade who are to be employed in aircraft component maintenance workshops on aircraft pulse system component repair and overhaul.

Suggested words for Statement of Attainment

These competencies from the MEA Aeroskills Training Package meet the requirements for employment of individuals with Certificate III or Certificate IV qualifications in an allied trade in aircraft component maintenance workshops on pulse system component repair and overhaul.

Custom Content Section

Not applicable.