



Australian Government

UEESS00004 Skill Set - Attend to Breakdowns in Hazardous Areas - Coal Mining

Release: 1

UEESS00004 Skill Set - Attend to Breakdowns in Hazardous Areas - Coal Mining

Modification History

Not Applicable

Description

Not Applicable

Pathways Information

Pathway

The units of competency in this skill set will contribute to the completion of relevant Diploma and Advanced Diploma qualifications from the UEE07 Electrotechnology Training Package.

Please consult the packaging rules of the relevant qualification for further advice.

Licensing/Regulatory Information

Not Applicable

Skill Set Requirements

Units

UEENEEM019A

UEENEEM080A

Target Group

Target Group

It is essential that anyone undertaking this skill set already holds the Competencies in attending to breakdowns in general electrical or instrumentation equipment mechanical plant/equipment service and maintenance at least AQF level 3 or equivalent.

Note :

This Skill Set is directly equivalent to the Unit 2.3 *Attend to breakdowns in hazardous areas* in the Australian/New Zealand Standard AS/NZS 4761.1; 2008 *Competencies for working with electrical equipment for hazardous areas (EEHA) Part 1: Competency Standards*.

Equivalence includes endorsement in the explosion-protection techniques listed in the Range statement of the unit
UEENEEM019A

Suggested words for Statement of Attainment

Suggested form of words for Statement of Attainment

This Skill Set from the UEE07 Electrotechnology Training Package meets the industry requirements for Attend to breakdowns in hazardous areas - coal mining