



Australian Government

UEESS00059 Hazardous Areas - Attend to Breakdowns in Hazardous Areas - Coal Mining

Release: 2

UEESS00059 Hazardous Areas - Attend to Breakdowns in Hazardous Areas - Coal Mining

Modification History

Release	Action	Core/Elective	Details	Points
2	Update	N/A	Mapped skill set requirements	

Description

Not applicable.

Pathways Information

The units of competency in this skill set will contribute to the completion of relevant Diploma and Advanced Diploma qualifications from the UEE11 Electrotechnology Training Package. Please consult the packaging rules of the relevant qualification for further advice.

Licensing/Regulatory Information

Readers should ensure that they have also read the part of the Training Package that outlines licensing and regulatory requirements.

Skill Set Requirements

UEENEEM019A Attend to breakdowns in hazardous areas - coal mining
UEENEEM080A Report on the integrity of explosion-protected equipment in a hazardous area

Target Group

It is essential that anyone undertaking this skill set already holds the Competencies in attending to breakdowns in general electrical or instrumentation equipment mechanical plant/equipment service and maintenance at least AQF level 3 or equivalent.

Note :

This Skill Set is directly equivalent to the Unit 2.3 Attend to breakdowns in hazardous areas in the Australian/New Zealand Standard AS/NZS 4761.1; 2008 Competencies for working with electrical equipment for hazardous areas (EEHA) Part 1: Competency Standards. Equivalence includes endorsement in the explosion-protection techniques listed in the Range statement of the unit UEENEEM019A

Suggested words for Statement of Attainment

This Skill Set from the UEE11 Electrotechnology Training Package meets the industry requirements for Attend to breakdowns in hazardous areas - coal mining

Custom Content Section

Not applicable.