



Australian Government

Assessment Requirements for FWPWPP2204 Repair veneer mechanically

Release: 1

Assessment Requirements for FWPWPP2204 Repair veneer mechanically

Modification History

Release	Comment
1	<p>Replaces equivalent unit FPIWPP2204B Repair veneer mechanically, which was first released with FPI11 Forest and Forest Products Training Package Version 2.2. This is the first release of this unit in the new standards format.</p> <p>Assessment requirements now specify the performance and knowledge evidence, as well as assessment conditions for this unit of competency. These sections simplify and replace components used in the previous unit format, including Required Skills and Knowledge, Evidence Guide and Range Statement</p>

Performance Evidence

A person demonstrating competency in this unit must satisfy all of the elements, performance criteria and foundation skills of this unit. If a specific volume or frequency is not stated below, then evidence must be provided that the following requirements have been performed on at least one occasion:

- repair veneer mechanically in line with an individual work orders that prescribe repair requirements and quantities for each job
- complete repairs for the following types of defects:
 - splits
 - splintered and missing edges
- for each of the above jobs, visually inspect veneer and re-classify its quality and use after repair.

Knowledge Evidence

A person competent in this unit must be able to demonstrate knowledge of:

- environmental protection practices for repairing veneer mechanically:
 - reducing water and energy use
 - cleaning plant, tools and equipment
 - disposing of, recycling and reusing timber and excess patch strips
- typical flow of material supply in and out of the repair area
- features of typical defects in single thickness veneer:
 - splits
 - splintered and missing edges

- typical work flow processes and repair techniques used to patch veneer to an acceptable level for continued use
- purpose, features and operation of veneer patching machinery
- key features of and applicable terminology for industry standard grades for re-classifying quality of repaired veneer
- organisational procedures specific to repairing veneer mechanically:
 - workplace health and safety with particular emphasis on equipment lock out and use of personal protective equipment
 - communication reporting lines
 - recording and reporting production outcomes and equipment faults.

Assessment Conditions

The following resources must be made available:

- veneer patching machinery with out-feed bins or trays
- personal protective equipment suitable for repairing veneer mechanically
- commercial single thickness veneer
- consumable veneer patch strips lined with an adhesive heat reactive backing
- manufacturers' instructions for use of equipment
- work order with specific instructions repairing veneer mechanically
- template documents for recording production outcomes and equipment faults
- relevant personnel for the purposes of communicating information
- organisational procedures for repairing veneer mechanically.

Competency is to be assessed in the workplace or a simulated environment that accurately reflects performance in a real workplace setting.

Assessor requirements

Assessors must:

- hold the appropriate assessor competency standards as outlined in regulations; and
- be able to demonstrate vocational competencies at least to the level being assessed; and
- be able to demonstrate how they are continuing to develop their VET knowledge and skills as well as maintaining their industry currency and assessor competence.

Links

Companion Volume implementation guides are found in VETNet -

<https://vetnet.gov.au/Pages/TrainingDocs.aspx?q=0d96fe23-5747-4c01-9d6f-3509ff8d3d47>