



Australian Government

CPC CST3009 Use computer-controlled static machinery to produce stone components

Release: 2

CPCST3009 Use computer-controlled static machinery to produce stone components

Modification History

- Release 2 Updated reference to general construction induction training program.
- Release 1 This version first released with CPC Construction, Plumbing and Services Training Package Release 5.0.
- Supersedes and is equivalent to CPCST3009A Use computer-controlled static machinery to produce stone components. Updated to meet the Standards for Training Packages 2012.

Application

This unit specifies the skills and knowledge required to produce hard and soft stone components using computer-controlled machines. It includes curved and straight moulds, levels and cuts.

This unit applies to stonemasons who work independently, in a team or under supervision and operate machinery relating to stonemasonry work in a workshop setting, on a new or existing structure.

A person working at this level would be expected to take responsibility for organising and completing tasks assigned to them without needing close supervision.

Completion of the general construction induction training program specified by the model Code of Practice for Construction Work is required for any person who is to carry out construction work. Achievement of *CPCWHS1001 Prepare to work safely in the construction industry* meets this requirement.

No licensing, legislative or certification requirements apply to this unit at the time of publication.

Pre-requisite Unit

CPCWHS2001 Apply WHS requirements, policies and procedures in the construction industry

Unit Sector

Stonemasonry

Elements and Performance Criteria

Elements describe the essential outcomes.

Performance criteria describe what needs to be done to demonstrate achievement of the element.

- | | |
|--|---|
| 1 Plan and prepare. | 1.1 Read, interpret and apply static machinery requirements from work instructions, job requirements and machine operator instructions. |
| | 1.2 Follow relevant information from workplace procedures, workplace safety and environmental documentation. |
| | 1.3 Determine job priorities and sequence job tasks in consultation with others on site. |
| | 1.4 Identify potential hazards and implement control measures. |
| | 1.5 Select and check condition of plant, equipment and tools and report damage or faults to relevant person. |
| | 1.6 Check conformity of materials against job requirements. |
| 2 Carry out data input. | 2.1 Select, fit correctly and use personal protective equipment (PPE) appropriate for job. |
| | 2.2 Determine and state programming terms, methods, limits and data storage capacity consistent with job requirements. |
| | 2.3 Write, enter and edit program to produce straight and circular movements, compensating for tool profiles. |
| 3 Transfer program to machine control. | 3.1 Identify and record methods of transferring program into machine memory. |
| | 3.2 Load program into machine memory using appropriate techniques to meet machine and job requirements. |
| 4 Operate loaded program to control machine. | 4.1 Conduct a program dry run in simulation mode to test alarm setting and edit using control station. |
| | 4.2 Take precautions to ensure production of silica dust is minimised. |

- 4.3 Produce specific work pieces using automatic mode.
- 5 Clean up.
 - 5.1 Clear the work area, and dispose of, reuse or recycle materials following workplace and environmental requirements.
 - 5.2 Clean tools and equipment, check for serviceability and report damage or faults.
 - 5.3 Store and secure tools and equipment following workplace procedures.

Foundation Skills

Foundation skills essential to performance are explicit in the performance criteria of this unit of competency.

Unit Mapping Information

Supersedes and is equivalent to CPC CST3009A Use computer-controlled static machinery to produce stone components

Links

Companion volumes to this training package are available at the VETNet website - <https://vetnet.gov.au/Pages/TrainingDocs.aspx?q=7e15fa6a-68b8-4097-b099-030a5569b1ad>